



## Echo v1.4.3 Release Notes

Version: 1.4.3 (623) November 14, 2011

Each Version 1.4.3 is a minor software update containing bug fixes and enhancements.

### v1.4.3 Enhancements

Echo no longer automatically starts fixture discovery when Echo is launched. In order to discover fixtures users must now select either the "Discover LWR Devices" option or the "Discover RDM Devices" option in the Device menu. Most High End Systems fixtures can be discovered using either option while fixtures from other manufactures should always be discovered using the RDM option.

#### **Bugs Fixed in v1.4.3.623:**

15540 Add support for Trackspot Bolt

15538 Remove Auto Discovery and add LWR/RDM discovery commands to the menu

15539 Issue with existing fixtures not being updated after a rediscover

---

The current version of the **SHOWPIX User Manual** and **Firmware** is available at:

[http://www.highend.com/support/LED/pixelation\\_luminaires/showpix/showpix.asp](http://www.highend.com/support/LED/pixelation_luminaires/showpix/showpix.asp)

The current version of the **StudioPix User Manual** and **Firmware** is available at:

[http://www.highend.com/support/LED/pixelation\\_luminaires/studiopix/studiopix.asp](http://www.highend.com/support/LED/pixelation_luminaires/studiopix/studiopix.asp)

The **Echo Software** and **User Manual** for updating the fixtures is at:

<http://www.highend.com/support/Echo/EchoSoftware.asp>