



Instructions for installing Obsession 1 hard drives with preloaded software.

PLEASE NOTE: When a new hard drive is installed into an Obsession processor, it will sometimes cause an "HDD CONTROLLER FAILURE" upon boot and the motherboard will beep twice then fail to boot. This may happen once or twice every ten boots (roughly). This is due to fact that a newer hard drive is installed into a very old system that cannot always keep up with the new hard drive. Unfortunately, we can no longer purchase the older style hard drives anymore. The problem can be remedied though, by simply powering off the unit by unplugging it and restarting.



Be sure to push delete at this screen which will take you to the following setup screen.



Make sure that your settings match these or your hard drive will not work.

AMIBIOS SETUP PROGRAM - BIOS SETUP UTILITIES
(C)1992 American Megatrends Inc., All Rights Reserved

STANDARD CMOS SETUP
ADVANCED CMOS SETUP
ADVANCED CHIPSET SETUP
AUTO CONFIGURATION WITH BIOS DEFAULTS
AUTO CONFIGURATION WITH POWER-ON DEFAULTS
CHANGE PASSWORD
AUTO DETECT HARD DISK
WRITE TO CMOS AND EXIT
DO NOT WRITE TO CMOS AND EXIT

Select the first option and press enter twice.

NOTE TO CUSTOMER: When a new hard drive is installed into an Obsession processor, it will sometimes cause an "HDD CONTROLLER FAILURE" upon boot and the motherboard will beep twice then fail to boot. This may happen once or twice every ten boots (roughly). This is due to fact that a newer hard drive is installed into a very old system that cannot always keep up with the new hard drive. Unfortunately, we can no longer purchase the older style hard drives anymore. The problem can be remedied though, by simply powering off the unit by unplugging it and restarting.